

## DIVISION OF OIL, GAS AND MINING

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340 801-359-3940 (Fax)

August 4, 1993

TO:

Minerals File

FROM:

Tony Gallegos, Reclamation Engineer adA

RE:

Site Inspection, Hansen Stone Quarries, Wesco Project, \$\( \frac{\$013}{001}, \)

Duchesne County, Utah

Date of Inspection:

July 21, 1993

Time of Inspection:

1130 - 1210

Conditions:

Overcast, windy

Participants:

Dan Powell, representing Hansen Stone Quarries; Tony

Gallegos, DOGM

Purpose of Inspection: To evaluate the current condition of the site.

The access road to the site is also used to access some private property further up the road. The quarry operations are visible from SR 191. There are currently three main quarry areas along a sandstone outcrop trending east-west. The guarries are excavations into an existing sandstone cliff which outcrops at this location.

A short spur road off of the main access road leads to the first and second quarry areas. This road is approximately 390 feet long and 10 feet wide. The cliff is approximately 8 to 10 feet high at this location. The disturbance at these guarry areas is approximately 210 feet long and 130 feet wide (including the disturbance above the cliff face).

The third guarry location is to the east of the first location. This third quarry site is accessed by another short spur road off the main access road. This spur road is approximately 0.1 mile long and 12 feet wide. The quarry area here is approximately 60 feet long and 15 feet wide.

jb cc:

Weston Hansen, Hansen Stone Quarries Jerry Mansfield, State Lands & Forestry

S13-01.ins

